

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated:

Certified that the existing building Govt. Inter collage (name of the building or premises) at Baluwakote, Dharchula, Pithoragarh, Pin-Code: 262576. (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+1					

The building is owned/occupied by Govt. Inter collage, Baluwakote, Dharchula, Pithoragarh, Pin-Code: 262576. (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Rural Works Department (Name of Department/ Govt.) on 29/01/2026 (date of inspection) in the presence of Principal Mr. Aansingh dhami (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 29/01/2026 for a period of 01 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. In future, if the building has any issues relating to any cracks, collapse and leakage of water it should be reported to concerned dept and immediate action should be taken.
2. Should Procure Fire Safety Certificate from Fire Dept their recommendations should be followed and updated regularly.
3. Original Documents of the Building should be kept safety

Issued on 29/01/2026 at Baluwakote by.

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Name:

Designation:

Name & Address of Department/ Office: प्रखण्ड- डीडोहट